

```
===== MXCHIP Manufacture Test =====  
Serial Number: 0000.0000.AT14  
App CRC: 9B12  
Bootloader Version: EMW3081 v3.0 921600  
Library Version: 30810002.056  
APP Version: AT Command on MICO OS ATV1.4, build at 18:01:18 Apr 27 2017  
Driver: 3081-v3.4C  
MAC: C8-93-46-FD-5C-E5  
Scan AP Success:  
  SSID: AP008, RSSI: -22  
  SSID: mxchip-offices, RSSI: -44  
  SSID: mxchip-rd, RSSI: -44  
  SSID: mxchip-offices, RSSI: -44  
  SSID: AP002, RSSI: -44  
  SSID: mxchip-rd, RSSI: -44  
  SSID: AP035, RSSI: -44  
  SSID: 360WiFi-YKM, RSSI: -48  
  SSID: AP003, RSSI: -48  
  SSID: mxchip-rd, RSSI: -50  
  SSID: wangzhilei, RSSI: -52  
  SSID: AP037, RSSI: -52  
  SSID: AP031-TOTO-A700R, RSSI: -54  
  SSID: AP011, RSSI: -56  
  SSID: wakaka, RSSI: -58  
  SSID: , RSSI: -60  
  SSID: William Xu, RSSI: -60  
  SSID: mxchip-offices, RSSI: -62  
  SSID: mxchip-offices, RSSI: -62  
  SSID: mxchip-rd, RSSI: -62  
  SSID: mxchip-offices, RSSI: -62  
  SSID: AP029, RSSI: -62  
  SSID: Pandora_ss, RSSI: -66  
  SSID: mxchip-offices, RSSI: -66  
  SSID: SWYANG, RSSI: -66  
  SSID: maoxian1234, RSSI: -66  
  SSID: mxchip-offices, RSSI: -66  
  SSID: mxchip-rd, RSSI: -66  
  SSID: 11, RSSI: -70  
  SSID: mxchip-rd, RSSI: -72  
  SSID: HHKL, RSSI: -72  
  SSID: mxchip-offices, RSSI: -72
```