

= MXCHIP Manufacture Test ===

Serial Number: 0000.0000.AT14

App CRC: 3E80

Bootloader Version: EMW3239_1 v3.0 921600

Library Version: 32390002.050

APP Version: AT Command on MICO OS ATV1.4, build at 11:08:49 Apr 26 2017

Driver: wl0: Jun 19 2016 22:40:05 version 7.45.45.17 (r644353)

Local Bluetooth Address: 04-78-63-A0-02-24

ADDR: 66:17:08:29:B3:05, RSSI: -88

ADDR: 4C:32:75:8A:17:BC, RSSI: -60

ADDR: AC:BC:32:83:AA:CE, RSSI: -92

ADDR: 4E:E7:6D:C6:5A:25, RSSI: -67

ADDR: 5B:07:A6:85:66:AE, RSSI: -61

ADDR: 5D:0E:E4:D3:67:CB, RSSI: -87

ADDR: 5E:CE:2C:EC:0D:F7, RSSI: -90

BLE scan complete

MAC 04-78-63-A0-02-25

Scan AP Success:

SSID: flashtest, RSSI: -50

SSID: Xiaomi.Berry, RSSI: -63

SSID: Xiaomi.Router, RSSI: -55

SSID: wifi, RSSI: -57

SSID: mxchip-rd, RSSI: -70

SSID: mxchip-guest, RSSI: -72

SSID: mxchip-offices, RSSI: -70

SSID: AP040, RSSI: -69

SSID: SWYANG, RSSI: -40

SSID: NETGEAR8, RSSI: -67

SSID: mxchip-rd, RSSI: -78

SSID: mxchip-offices, RSSI: -78

SSID: YouXX, RSSI: -60

SSID: , RSSI: -63

SSID: AP039, RSSI: -62

SSID: William Xu, RSSI: -78

SSID: TP-LINK_110, RSSI: -73

SSID: KMK-P500C_071C, RSSI: -74

SSID: MXCHIP_1D0263, RSSI: -90

SSID: GM, RSSI: -65

SSID: mxchip-offices, RSSI: -75

SSID: mxchip-rd, RSSI: -74

SSID: mxchip-rd, RSSI: -39

SSID: mxchip-offices, RSSI: -40

SSID: mxchip-offices, RSSI: -68

SSID: mxchip-rd, RSSI: -68

SSID: OrayBox-94A2, RSSI: -58

SSID: AP007, RSSI: -67

SSID: mxchip-offices, RSSI: -40

SSID: mxchip-rd, RSSI: -40

QC.txt

SSID: mxchip-offices, RSSI: -57
SSID: mxchip-rd, RSSI: -58
SSID: biubiubiubiubiu, RSSI: -74
SSID: MICO_OTA_AP_TEST, RSSI: -55

MXCHIP_MFMODE>